



Southcoates

Southcoates Conducted on 25th Jan, 2019 By Info hrc

| | | |
|------------------|--------------|-----------------|
| Inspection score | Failed items | Created actions |
| 85.71% | 0 | 0 |

| |
|---|
| PLOT NUMBER 61 |
| CLEAN TYPE Sparkle Clean |
| Conducted on 📅 25th Jan, 2019 ⌚ 09:23 AM GMT |
| Location Unanswered |
| Carried out by: Jazz bob |

Audit

85.71%

Is the plot ready for cleaning?

Yes

If no, please select

Unanswered

Are there other trades present in the plot?

No

Is the Kitchen fully fitted?

Yes


Photos



Is the sanitary fully fitted?

Yes

Photos



All internal windows completed?

Yes


Photos



All external window completed?

Yes

Photos



Any additional notes

Plot handed to us in a great condition. All previous clean documented and checked prior to cleaning. No problems to mention. Plot walked with site manager prior to signing off.

Additional Photos

Photos



Customer refused to check plot:

Unanswered



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8




Photo 9





Photo 11

Photo 10




Photo 12



Photo 13



Photo 15



Photo 14



Photo 16

Photo 17




Photo 18

Photo 19





Photo 20



Photo 21

Photo 22




Photo 23



Photo 25




Photo 24




Photo 26

